

Fig 1




Fig 2




Fig 3




Fig 4




Fig 5




Fig 6




Fig 7




Fig 8

Lög:	sensor
2003-04-16 11:02:	Sensor installed by Henrik Larne
Time:	Entry:
2003-04-16 11:02	Sensor installed by Henrik Larne
	New Entry Save Log Close

Fig 9





Fig 10

Main Sensors Administration Mail Demo Help:	Z	
WeSpot lab outside		O Wespot
Event List Sensor Settings PC Settings Event History Snapsh		<b>⊙</b> wespot
III - IIII - III -	oti	
⊠ Set up		
☑ Image failure		
☑ Cover/Zone shift ☑ Relay activation count		
■ Auto adapt		
		9
III TA fee will be and fee and		
Datails Details		1.14
· ·		
Apply		
		1

Fig 11

: Event Supervision : Main Sensors Administration	n Mail Demo H	lëlp:		<del>.</del> .	
WeSpot lab outside				▼.	Olympia
Event List Sensor Settings PC Settings Event History Snapsho					⊙ wespot
Auto-play:  Set up Image failure Cover/Zone shift Relay activation count Auto adapt Continous door hold open After Hour Surveillance  Event playing: Still image preview  Change PC Time	Signal: □Signal 國優 □Signal 國優 □Signal 國優 □Signal 國優	Storage:  ☐ Store	E-mail: person@ Apply I	Pabo	

Fig 12



**Fig 13**